



Motor Motorcycle Brake Shoes 1110020 With Lining For TVS Apache RTR160/180

Our Product Introduction

for more products please visit us on waycmoto.com

Basic Information

- Place of Origin: Guangdong, China
- Brand Name: WAY-C
- Model Number: TVS KING
- Minimum Order Quantity: 200 pieces
- Price: \$15.00/pieces 200-1000 pieces
- Packaging Details: BOX+CARTON
- Delivery Time: 30-45days
- Payment Terms: L/C, D/A, D/P, T/T, Western Union, MoneyGram
- Supply Ability: 200000 Piece/Pieces per Month



Product Specification

- Model: TVS Apache RTR160/180
- Product Name: Motorcycle Brake Shoes
- MOQ: 200 PCS
- Material: Semi-metallic, Low-metallic, Ablation, Ceramic
- Quality: High Quality
- Shipping: Sea Transport, Air Transport, Air Express
- Port: NANSHA/HUANGPU, GUANGZHOU
- Parts NO: 1110020
- Highlight: Motorcycle Brake Shoes, Brake Shoes 1110020



More Images



Product Description

1110020 TVS Apache RTR160/180 Motor Motorcycles Brake Shoes with Lining

Products Description

Product name	Brake Shoes
Model	TVS Apache RTR160/180
Materials	Semi-metallic,Low-metallic
Parts NO	1110020
Packing	Box
Shipping	Sea/Air
Place of origin	Guangzhou,China





The brake shoe refers to the accessory that is pushed outward by the action of the brake cam or push rod to suppress the brake drum and exert braking effect. Its shape is like a half-moon shape. During braking, the brake cylinder pushes the two brake shoes outward and rubs against the brake drum. After braking, the return spring contracts to return the shoes to their original position.

Brake shoes generally consist of two parts: an iron lining plate and friction material. Do not wait until the friction material part is worn away before replacing the shoe. For example, the front brake pads of the Jetta are 14 mm thick when new, but the limit thickness for replacement is 7 mm, including more than 3 mm of iron lining thickness and nearly 4 mm of friction material thickness. Some vehicles have a brake shoe alarm function. Once the wear limit is reached, the instrument will alarm to prompt you to replace the shoe. Shoes that have reached their service limit must be replaced. Even if they can still be used for a period of time, they will reduce the braking effect and affect driving safety.

PACKING & SHIPPING

GUANGZHOU WAY-C TRADING CO.,LTD.



5-7 working days
WWW.TNT.COM



5-7 working days
WWW.EMS.COM.CN



5-7 working days
WWW.DHL.COM



5-7 working days
WWW.UPS.COM



5-7 working days
WWW.FEDEX.COM



Why Choose Us

Why choose us?

- ◆ 1. High quality: Using high quality material and establishing a strict quality control system, assigning specific persons in charge of each part of production, from raw material purchase to assembly.
- ◆ 2. Professional models for motorcycle parts and three wheeler parts , we have one group to focus on the new models parts , so welcome to OEM and ODM orders
- ◆ 3. Fast dispatch: Most of the products are in stock. Quality below 100pcs can be delivered within 15 days.
- ◆ 4. Small order accepted: Low MOQ accepted. 50pcs are available.

**GUANGZHOU WAY-C TRADING CO.,LTD**[+86 18561893286](tel:+8618561893286)522509400@qq.comwaycmoto.com

NO.356 Baiyun Motorcycle Parts Market, Zengcha Road, Baiyun District, Guangzhou