

Guangdong, China

WAY-C

Moto Engine Cylinder Block Assy 11210-34J00-0F0 For Suzuki GIXXER GXS

Basic Information

- Place of Origin:
- Brand Name:
- Model Number:
- Minimum Order Quantity:
- Price:
- Packaging Details:
- Delivery Time:
- Payment Terms:
- Supply Ability:
- Suzuki GIXXER GXS 36 pieces \$3.00/pieces 36-1000 pieces Box+Carton 30-45days L/C, D/A, D/P, T/T, Western Union, MoneyGram 200000 Piece/Pieces per Month



Product Specification

- Model:
- Product Name:
- MOQ:
- Material:
- Quality:
- Shipping:
- Port:
- Parts NO:
- Highlight:

Suzuki GIXXER GXS
Cylinder Block
36 PCS
Iron
High Qaulity
Sea Transport.Air Transport Air Express
NANSHA/HUANGPU, GUANGZHOU
11210-34J00-0F0

Moto Cylinder Block Assy, Suzuki Cylinder Block Assy, 11210-34J00-0F0







Our Product Introduction

Product Description

11210-34J00-0F0 Motorcycle Engine Cylinder Block for Suzuki GIXXER GXS

Products Description

Product name	Motorcycle Cylinder Block	
Model	Suzuki GIXXER GXS	
Parts NO	11210-34J00-0F0	
Packing	Box	
Shipping	Sea/Air	
Place of origin	Guangzhou,China	



The cylinder sleeve of a motorcycle refers to the complete set of three components: cylinder block, piston, and piston ring. Some also come with a piston pin. The cylinder sleeve refers to a set. Generally, when a motorcycle burns engine oil, it is best to replace the cylinder block, piston, and piston rings as a whole set. Replacing just one piece individually is not effective and may cause the engine to burn oil again soon. Moreover, replacing the entire set of parts will interfere with each other. The matching between them is better and errors are less likely to occur. When repairing or selling parts, a set of cylinder block, piston and piston ring is called "cylinder set".

Motorcycle cylinder lining refers to the process of replacing the motorcycle engine block. When a motorcycle's engine block shows severe wear, cracks, or other damage, a cylinder lining operation may be required to repair or replace the block.



