

Guangdong, China

WAY-C

11210H3H010H000 Motorcycle Engine Cylinder Block Kit For HAOJUE XPRESS

Basic Information

- Place of Origin:
- Brand Name:
- Model Number:
- Minimum Order Quantity:
- Price:
- Packaging Details:
- Delivery Time:
- Payment Terms:
- Supply Ability:
- HAOJUE XPRESS 36 pieces \$15.00/pieces 200-990 pieces Box+CARTON 30-45days L/C, D/A, D/P, T/T, Western Union, MoneyGram 20000 Piece/Pieces per Month



Product Specification

Model:

• MOQ:

• Material:

• Quality:

Shipping:Port:

• Product Name:

- HAOJUE XPRESS Cylinder Block Kit 100PCS Iron High Qaulity Sea Transport.Air Transport Air Express NANSHA/HUANGPU, GUANGZHOU
- Parts NO: 11210H3H010H000
- Highlight:

NANSHA/HUANGPU, GUAN 11210H3H010H000

11210H3H010H000, Engine Cylinder Block Kit, Motorcycle Cylinder Block Kit

Our Product Introduction

11210H3H010H000 Motorcycle Engine Cylinder Block Kit For HAOJUE XPRESS

Products Description

Product name	Cylinder Block Kit
Model	HAOJUE XPRESS
Materials	Iron
Parts NO	11210H3H010H000
Packing	Вох
Shipping	Sea/Air
Place of origin	Guangzhou,China



HAOJUE XPRESS motorcycle is a model produced by Haojue Motorcycle. Information about cylinder block kit is as follows:


The role of the liner: The liner is a component located in the engine block and is used to provide sealing and friction reduction between the piston and the cylinder. It protects the engine block and also provides good lubrication and sealing conditions required for piston movement.

Material and manufacturing: The sleeve cylinder is usually made of high-strength aluminum alloy material to meet the high temperature and high pressure working environment. The manufacturing process often involves precise machining and coating techniques to ensure the dimensional accuracy and surface smoothness of the sleeves.

Replacement of cylinder liners: In some cases, engine cylinder liners may need to be replaced when they are worn, damaged, or have lost their sealing properties.

Maintenance Precautions: To ensure proper operation and longevity of the liner, it is important to regularly change the engine oil and filter elements, and follow the manufacturer's maintenance recommendations. Maintaining normal engine operating temperatures and avoiding excessive acceleration and high-load operation also help reduce cylinder wear.





NO.356 Baiyun Motorcycle Parts Market, Zengcha Road, Baiyun District, Guangzhou